

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No 128188

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080115-6

RECEIVED FROM

DATE REC'D 1-1-57

P. O. NO.

62206-1

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	B. I. V. OUT CODE NO.	ACCT. OR W. O. NO.
	322	000000	10114	0	0	00	00	02	

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
10	791702-4 BALL BEARING PARTIAL 1402	10		

RECEIVED BY: *[Signature]* INSPECTED BY: *[Signature]* DATE: 1/1/57

REJECTS RETURNED  
ON SHIP. MEMO NO.

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128196

RECEIVED FROM

DATE REC'D 1-23-55

P. O. NO. 6410

VENDOR PACKING SLIP NO.

4947

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	B. I. V. OUT CODE NO.	ACCT. OR W. O. NO.
	322	000000	18073	0	0	00	00	02	

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
05	730125-1 21 50556 BOLLER TRAIL	5		

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080115-6

RECEIVED BY: *[Signature]* INSPECTED BY: *[Signature]* DATE: 1/24/57

REJECTS RETURNED  
ON SHIP. MEMO NO.